

Mexico – Swift River Site

This is a secondary site that was essentially replaced in the late summer of 2010 by a new ramp described above.. This site has a FERC Part 8 sign but is not marked with Androcoggin River Trail signage.

Location: Mexico, Maine Off Route 2 near downtown Mexico. Going westerly on Rt. 2, site is on right just before crossing Swift River bridge into Rumford.

Owner: Brookfield. Manager: Brookfield

Launch facilities:

Heavily silted concrete ramp into shallow water. No access for trailered boats. Launch is under bridge. Water in Swift River can be very shallow during low flows. Paddlers may have to walk their boat to deeper water in the Swift River.

Parking:

Six vehicles; no suitable space for trailers.